

# 22 Apr 2019 / 3B7KF23642M238968 / Jaunter X5


Pre-delivery Inspection Checklist Conducted on 22nd Apr, 2019 By SafetyCulture Staff

Complete


Inspection score	Failed items	Created actions
95.73%	5	3
Site		
Sydney		
Car Make/Model		
Jaunter X5		
Vehicle Identification Number		
3B7KF23642M238968		
Dealer		
Shining Motors, Inc.		
Location		
722 Charles St., Detroit, MI 48226		
Inspected by		
Charista Perez		
Conducted on		
☐ 22nd Apr, 2019 ③ 11:44 AM +	+08	


Failed items 5 Failed

#### Pre-delivery Inspection Checklist / Wheels & Tires



#### Pre-delivery Inspection Checklist / Engine Compartment






Pre-delivery Inspection Checklist / Road Test




### Pre-delivery Inspection Checklist / Convenience




**Actions** 3 Actions


SafetyCulture Staff created a High priority action
To Do
Refill engine oil
The engine oil level was below acceptable levels, so it must be refilled before the road test.
Pre-delivery Inspection Checklist / Engine Compartment
Pre-delivery inspection checklist / Engine compartment
Engine oil level
SafetyCulture Staff created a High priority action
To Do 22nd Apr, 2019 8:00 AM +08
Replace radiator cap
The cap was loosely attached to the radiator, as if the cap was only sitting on top of the radiator but not really closed. It
could cause signs of overheating during the road test.
Pre-delivery Inspection Checklist / Engine Compartment
Radiator & cap
SafetyCulture Staff created a High priority action
To Do
23/d Aβ1, 2019 0.00 AW1 100
Locate spare tire
The spare tire wasn't in the rear compartment when I checked.
Pre-delivery Inspection Checklist / Wheels & Tires
Spare tire




# **Body Exterior**




Wheels & Tires 1 Failed 1 Actions





### **Interior & Luggage Compartment**



#### **Electrical Controls**









#### **Brakes**

Master cylinder security	Pass
Fluid leaks	Pass
Servo/power system	Pass
Flexible hoses	Pass
Pipes/unions & connections	Pass
Notes Properly routed	
Discs & pads	Pass
Hand brake operation/adjustments	Pass
Hand brake linkage	Pass
Pedal/linkage	Pass

### **Engine Compartment**

2 Failed 2 Actions





Cold starting	Pass
Fast idle when engine cold	Pass
Noise level when engine cold	Pass
Excess fumes/smoke	Pass

### **Clutch & Transmission**

Fluid/oil leaks	Pass
Cables/adjustment	Pass
Hydraulic system	Pass
Linkages (check for signs of wear)	Pass
Casings	Pass
Mountings	Pass
Drive shaft assemblies	Pass
Universal & sliding joints	Pass
Clutch backlash	Pass
Rubber gaiters	Pass
Propshaft(s)	Pass
Bearings & supports	Pass

# **Exhaust System**

Inlet manifold	Pass
Outlet manifold	Pass
Pipes	Pass
Photos  Photo 17  Photo 18	
Silencer(s)	Pass
Heat shields & mountings	Pass
Joints & couplings	Pass
Catalytic converter	Pass
Overall system condition	Pass

# Fuel System

Fuel tank	Pass
Fuel tank fixings	Pass
Fuel lines	Pass
Breather pipes	Pass
Evidence of leaks	Pass

# Suspension, Underframe & Steering

Engine underside leaks	Pass
Steering joints & ball joints	Pass
Steering rack	Pass
Chassis members	Pass
Power steering	Pass
Wheels, hubs & bearings	Pass
Springs & suspension unit	Pass
Pipes & hoses	Pass
Dampers & bushes	Pass
Gaiters	Pass
Sub frames & mountings	Pass
Suspension arms, mountings & fixings	Pass
Tie bars & anti-roll bars	Pass
Anti roll-bar	Pass
Evidence of floor/chassis corrosion	Pass
Bumper stops & gaiters	Pass

Road Test 1 Failed

Engine - performance	Pass
Engine - noise	Pass
Engine - excessive fumes or smoke	Pass
Evidence of overheating	Fail
Notes  Due to loose radiator cap up for replacement	
Gearbox operation & noise level	Pass
Final drive operation & noise level	Pass
Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	Pass
Footbrake operation	Pass
Hand brake operation	Pass
Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass

Convenience 1 Failed



#### Completion

Additional Observations

Overall, the vehicle is in good working condition. Must replace the radiator cap and perform another road test before handing it over to the customer.

Name & Signature of Vehicle Inspector

Charista Perez

22nd Apr, 2019 12:50 PM +08

Photos 18 Photos





Photo 1





Photo 3



Photo 4

Photo 2



Photo 5



Photo 8



Photo 7



Photo 10



Photo 9



Photo 12



Photo 11



Photo 14



Photo 13



Photo 16





Photo 18

Photo 15



Photo 17