



Davidson Corp. / Manufacturing / Dylan Byers / 21 May 2019

Basic Hazard Identification Template Conducted on 21st May, 2019 By SafetyCulture Staff

Complete

Failed items	Created actions
2	1
Department / Area of work Davidson Corp. / Manufacturing	
Date of Inspection 📅 21st May, 2019 ⌚ 9:50 AM +08	
Conducted by Dylan Byers	
Location Arvada, WY 82831, USA	

Inspection / Hazard Identification / Hazard / Hazard 1

Risk rating	Serious
Notes Exit signs must be properly illuminated by a reliable light source, with a minimum of 5 foot-candles on the illuminated surface.	
Actions	
To Do See what's wrong and perform necessary actions	

Inspection / Hazard Identification / Hazard / Hazard 2

Risk rating	Serious
-------------	---------

Actions

1 Actions

SafetyCulture Staff created a Medium priority action

To Do

📅 25th May, 2019 8:00 AM +08

Please check this out

See what's wrong and perform necessary actions

Inspection / Hazard Identification / Hazard / Hazard 1


Risk rating

Hazard Identification

Hazard


Hazard 1

1 Failed 1 Actions



Specify hazard Exit sign	
Hazard type	Safety hazard
Describe hazard Exit sign doesn't turn on when tested	
Risk rating	Serious
Notes Exit signs must be properly illuminated by a reliable light source, with a minimum of 5 foot-candles on the illuminated surface.	
Actions	To Do See what's wrong and perform necessary actions
Take or attach photo of hazard	
Photos	
Photo 1	

Hazard 2


1 Failed

Specify hazard Shock hazard	
Hazard type	Other
Please specify Electrical hazard	
Describe hazard possible shock hazard from outlet #5-A in level 1 due to reversed polarity	
Risk rating	Serious
Take or attach photo of hazard	
Photos	
	
Photo 2	

Hazard 3

Specify hazard Fire extinguisher	
Hazard type	Safety hazard
Describe hazard Fire extinguisher #8 was found on the floor when it should be placed at its container	
Risk rating	Minor
Notes Already placed it on its respective place & additionally conducted a fire extinguisher inspection	
Take or attach photo of hazard	
Photos	
	
Photo 3	Photo 4

Completion

Comments / Recommendations Overall, it was a good inspection. No major hazards were found but it is still important to bring utmost attention to the hazards identified above. Fire extinguisher has been examined so no need to conduct separate inspection.	
Name & Signature of Safety Inspector	
	Dylan Byers 21st May, 2019 12:10 PM +08

Photos

4 Photos



Photo 1



Photo 2



Photo 3



Photo 4