



03 May 2019 / Samantha Leibnitz / Welding

Visual Inspection Report Form Conducted on 3rd May, 2019 By SafetyCulture Staff

Complete

Failed items

2

Site Sydney
Company Steelix Manufacturing Ltd.
Department Welding
Address 3428 Hillcrest Lane, Primmer CA
Prepared by Samantha Leibnitz
Conducted on 📅 3rd May, 2019 ⌚ 2:04 PM +08

Failed items

2 Failed

Inspection / Visual Inspection Report Form / Part / Part 3

Defect Criteria

Fail

Inspection / Visual Inspection Report Form / Part / Part 5


Defect Criteria

Fail


Visual Inspection Report Form

Part

Part 1


ID & Location 01 / AE03	
Take/attach photos	
Photos 	
Photo 1	
Defect Criteria	Pass

Part 2


ID & Location 02 / AE03	
Take/attach photos	
Photos 	
Photo 2	
Defect Criteria	Pass

Part 3

1 Failed


ID & Location 03 / AE03	
Take/attach photos	
Photos	
	
Photo 3	
Defect Criteria	Fail
Identify visual defect/s.	
Incomplete fusion Arc strikes	

Part 4


ID & Location 04 / AE03	
Take/attach photos	
Photos	
	
Photo 4	
Defect Criteria	Pass

Part 5

1 Failed

ID & Location 05 / AE03	
Take/attach photos	
Photos	
	
Photo 5	
Defect Criteria	Fail
Identify visual defect/s.	
Burn through Under cut	

Part 6

ID & Location 06 / AE03	
Take/attach photos	
Photos	
	
Photo 6	
Defect Criteria	Pass

Completion

Additional Observations

We should keep on using iAuditor for our visual inspections to easily identify visual defects!

Quality Assurance Inspector Name & Signature

A handwritten signature in black ink, appearing to read 'Samantha Leibnitz', enclosed in a rounded rectangular box.

Samantha Leibnitz

3rd May, 2019 2:26 PM +08



Photo 1



Photo 2



Photo 3




Photo 5



Photo 4



Photo 6