



Property Inspection Report Form

12 Feb 2021 / SafetyCulture Staff

Complete

Score	0%	Failed items	0	Actions	0
Complete Address				2 Lacey St, Surry Hills NSW 2010, Australia	
Date					12th Feb, 2021
Prepared by					SafetyCulture Staff

Inspection

Livability - Neighborhood Rating

A

Room Additions to Home

Yes

Exterior photo of room addition

Roof Condition

Good - No signs of wear

Exterior siding

Brick

Exterior Condition - Siding repair, pressure wash, peeling paint, etc...

Front of house showing roof

Exterior - front, back, roof, street view

Interior Condition - Flooring, walls, paint, any visible damage

Appliances Present

Refrigerator

Oven/Stove

Microwave

Dishwasher

Kitchen - Appliances condition, cabinets, counter tops

Bathrooms - vanities, mirrors, fixtures, tub/shower, toilet

Wiring

Aluminum

Photo of wiring showing material

Windows

Double Pane

Photo of window showing condition

Number of windows

Measurements of windows

Number of interior doors

Measurements of doors

Further Important Notes on Property pertinent to the potential value, condition, and repairs needed

Sign Off

Name and Signature