



Annual Fire Extinguisher Inspection

Bigbang Exchange Building / Eden Chauncey / 15
Aug 2022

Complete

Score	80%	Flagged items	1	Actions	1
-------	-----	---------------	---	---------	---

Client / Site

Bigbang Exchange Building

Location

QHFG+68 Gravesboro, CA, USA

Conducted on

15.08.2022 14:55 PST

Prepared by

Eden Chauncey

Flagged items & Actions

1 flagged, 1 action

Flagged items

1 flagged, 1 action

Audit / Dry Powder Extinguishers / Maintenance

General Condition of the extinguishers mechanical parts

Poor

Two of the extinguishers have physical dents.

To Do | Assignee SafetyCulture Staff | Priority High | Due 01.08.2022 15:14 PST | Created by SafetyCulture Staff

Check further if these are still good to be kept or should be replaced altogether.

Other actions

0 actions

Audit

1 flagged, 1 action, 80%

INSTRUCTIONS

- 1. Start by filling out the necessary information.
- 2. Assess the following by answering: "Good, Fair or Poor" on the questions below.
- 3. Add photos, notes and identified defects by clicking on the paperclip icon.
- 4. To add a Corrective Measure click on the paperclip icon then "Add Action", provide a description, assign to a member, set priority, and due date.
- 5. Complete audit by providing digital signature.
- 6. Share your report by exporting as PDF, Word, Excel or Web Link

Extinguishers present in the premise

Dry Powder

Foam

Foam Extinguishers

100%

No. of Foam Extinguishers

3

Take a photo



Photo 1

Maintenance

100%

General Condition of the extinguishers mechanical parts

Fair

General Condition of the extinguishers agent

Good

General Condition of the extinguishers expelling means

Good

Dry Powder Extinguishers

1 flagged, 1 action, 66.67%

No. of Dry Powder Extinguishers

4

Take a photo



Maintenance

1 flagged, 1 action, 66.67%

General Condition of the extinguishers mechanical parts

Poor

Two of the extinguishers have physical dents.

To Do | Assignee SafetyCulture Staff | Priority High | Due 01.08.2022 15:14 PST | Created by SafetyCulture Staff

Check further if these are still good to be kept or should be replaced altogether.

General Condition of the extinguishers agent

Good

General Condition of the extinguishers expelling means

Good

One of the extinguishers

Summary and Completion

Total Number of Extinguishers inspected within the premises. (Interior and Exterior)

7

Total Number of Repaired Extinguishers

2

Total Number of Replaced Extinguishers

1

One of the Dry Powder Extinguishers is in a bad shape so it needed replacement.

Overall comments of the 12 month inspections

Generally, the fire extinguishers in the building are well-kept and well-maintained. Just make sure to also do random checks moving forward, to quickly identify if any of them needs immediate replacement.

I hereby confirm that the Annual Fire Extinguisher Inspection was performed by an approved extinguisher servicing company.

Name and Signature of Inspector



Eden Chauncey
15.08.2022 15:19 PST

Appendix



Photo 1



Photo 2