



Safety Data Sheet Template

conducted for

Anionic Anti-Sludge Agent

Conducted on

13 Mar 2019 07:50 PM

Prepared by

Glendale Industries, Inc.

Location

Statenville, GA, 31648


Completed on

13 Mar 2019 08:23 PM

Score

0/0.0 - 0.00%

Inspection

Question	Response	Details
SECTION 1: IDENTIFICATION		
1.1 Product Identifier		
Product Form	Mixture	
Product Name	Product A (For sample report only)	
Synonyms	Anionic Anti-Sludge Agent	
1.2 Intended Use of the Product		
Use of the substance/mixture	Anti-Sludge Agent. For professional use only.	
1.3 Name, Address, and Telephone of the Responsible Party/Company	Glendale Industries, Inc. 1234 Anywhere Way Anytown, US 12345	
Emergency Telephone Number	1.888.362.2007 - For Chemical Emergency, Spill, Leak, Fire, Exposure, or Accident, call GLENTREC Day or Night	
SECTION 2: HAZARDS IDENTIFICATION		
2.1 Classification of the Substance or Mixture (GHS-US Classification)	GHS-US Classification Flam. Liq 2 - H225 Skin Corr. 1B - H314 Eye Dam. 1 - H318 STOT SE 3 - H336 Note: See full text of hazard classes and H-Statements in Section 16	
2.2 Label Elements (GHS-US Labeling)		
Hazard Pictograms (GHS-US)		
 <p style="text-align: center;">GHS05 Appendix 1</p>		
Signal Word (GHS-US)	Danger	


Question	Response	Details
Hazard Statements (GHS-US)		H225 - Highly flammable liquid and vapor. H314 - Causes severe skin burns and eye damage. H318 - Causes serious eye damage. H336 - May cause drowsiness or dizziness.
Precautionary Statements (GHS-US)		P210 - Keep away from heat, sparks, open flames, hot surfaces. - No smoking. P240 - Ground/Bond container and receiving equipment. P241 - Use explosion-proof electrical, ventilating, and lighting equipment. P242 - Use only non-sparking tools. P243 - Take precautionary measures against static discharge. P260 - Do not breathe vapors, mist, spray. P264 - Wash hands, forearms, and other exposed areas thoroughly after handling. P271 - Use only outdoors or in a well-ventilated area. P280 - Wear protective gloves, protective clothing, eye protection, face protection, respiratory protection. P301+P330+P331 - If swallowed: rinse mouth. Do NOT induce vomiting. P303+P361+P353 - If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. P304+P340 - If inhaled: Remove person to fresh air and keep at rest in a position comfortable for breathing. P305+P351+P338 - If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P310 - Immediately call a poison center or doctor.
2.3 Other Hazards		Flammable vapors can accumulate in head space of closed systems. Exposure may aggravate pre-existing eye, skin, or respiratory conditions. Repeated or prolonged skin contact may cause dermatitis and defatting.
2.4 Unknown Acute Toxicity (GHS-US)		No data available.
SECTION 3: COMPOSITION/INFORMATION ON INGREDIENTS		
3.1 Substance		Not applicable
3.2 Mixture (Include percentage of components)		50% Isopropyl alcohol 50% Benzenesulfonic acid, 4-dodecyl
Component (include percentage & GHS-US classification)		

Question	Response	Details
Chemical component 1		
	50% Isopropyl alcohol Flam. Liq. 2, H225 Eye Irrit. 2A, H319 STOT SE 3, H336	
Chemical component 2		
	50% Benzenesulfonic acid, 4-dodecyl Skin Corr. 1B, H314 Eye Dam. 1, H318	
Full text of H-phrases: see section 16		
SECTION 4: FIRST AID MEASURES		
4.1 Description of First-aid Measures	<p>First-aid Measures General: Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice (show the label where possible).</p> <p>First-aid Measures After Inhalation: Obtain medical attention if breathing difficulty persists. When symptoms occur: go into open air and ventilate suspected area.</p> <p>First-aid Measures After Skin Contact: Remove contaminated clothing. Immediately flush skin with plenty of water for at least 30 minutes. Immediately call a POISON CENTER or doctor. Wash contaminated clothing before reuse.</p> <p>First-aid Measures After Eye Contact: Rinse cautiously with water for at least 30 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get immediate medical advice/attention</p> <p>First-aid Measures After Ingestion: Rinse mouth. Do not induce vomiting. Obtain medical attention.</p>	

Question	Response	Details
4.2 Most Important Symptoms and Effects Both Acute and Delayed		<p>Symptoms/Injuries: Causes severe skin burns and eye damage. Causes serious eye damage. May cause drowsiness and dizziness.</p> <p>Symptoms/Injuries After Inhalation: Inhalation may cause immediate severe irritation progressing quickly to chemical burns.</p> <p>May be corrosive to the respiratory tract. High concentrations may cause central nervous system depression such as dizziness, vomiting, numbness, drowsiness, headache, and similar narcotic symptoms.</p> <p>Symptoms/Injuries After Skin Contact: Causes severe irritation which will progress to chemical burns.</p> <p>Symptoms/Injuries After Eye Contact: Causes severe irritation which will progress to chemical burns. Causes permanent damage to the cornea, iris, or conjunctiva.</p> <p>Symptoms/Injuries After Ingestion: May cause burns or irritation of the linings of the mouth, throat, and gastrointestinal tract.</p> <p>Chronic Symptoms: None known</p>
4.3 Indication of Any Immediate Medical Attention and Special Treatment Needed		<p>If exposed or concerned, get medical advice and attention. If medical advice is needed, have product container or label at hand.</p>
SECTION 5: FIRE-FIGHTING MEASURES		
5.1 Extinguishing Media		<p>Suitable Extinguishing Media: Dry chemical powder, alcohol-resistant foam, carbon dioxide (CO₂). Water may be ineffective but water should be used to keep fire-exposed container cool.</p> <p>Unsuitable Extinguishing Media: Do not use a heavy water stream. Use of heavy stream of water may spread fire.</p>
5.2 Special Hazards Arising From the Substance or Mixture		<p>Fire Hazard: Highly flammable liquid and vapor.</p> <p>Explosion Hazard: May form flammable or explosive vapor-air mixture. When mixed with air and exposed to an ignition source, flammable vapors can burn in the open or explode in confined spaces. Being heavier than air, vapors may travel long distances to an ignition source and flash back. Runoff to sewer may cause fire or explosion hazard.</p> <p>Reactivity: Reacts violently with strong oxidizers.</p> <p>Increased risk of fire or explosion.</p>

Question	Response	Details
5.3 Advice for Firefighters		<p>Precautionary Measures Fire: Exercise caution when fighting any chemical fire.</p> <p>Firefighting Instructions: Use water spray or fog for cooling exposed containers. Remove containers from fire area if this can be done without risk. In case of major fire and large quantities: Evacuate area. Fight fire remotely due to the risk of explosion. Do not breathe fumes from fires or vapors from decomposition.</p> <p>Protection During Firefighting: Do not enter fire area without proper protective equipment, including respiratory protection.</p> <p>Hazardous Combustion Products: Thermal decomposition generates: Carbon oxides (CO, CO₂). Sulfur oxides. Corrosive vapors.</p> <p>Other Information: Do not allow run-off from fire fighting to enter drains or water courses.</p>
SECTION 6: ACCIDENTAL RELEASE MEASURES		
6.1 Personal Precautions, Protective Equipment and Emergency Procedures		<p>General Measures: Do not get in eyes, on skin, or on clothing. Do not breathe vapor, mist or spray. Keep away from heat, hot surfaces, sparks, open flames, and other ignition sources. No smoking. Use special care to avoid static electric charges. Use only non-sparking tools.</p>
6.1.1 For Non-Emergency Personnel		<p>Protective Equipment: Use appropriate personal protective equipment (PPE).</p> <p>Emergency Procedures: Evacuate unnecessary personnel. Stop leak if safe to do so.</p>
6.1.2 For Emergency Personnel		<p>Protective Equipment: Equip cleanup crew with proper protection.</p> <p>Emergency Procedures: Eliminate ignition sources. Ventilate area. Upon arrival at the scene, a first responder is expected to recognize the presence of dangerous goods, protect oneself and the public, secure the area, and call for the assistance of trained personnel as soon as conditions permit.</p>
6.2 Environmental Precautions		<p>Prevent entry to sewers and public waters.</p>

Question	Response	Details
6.3 Methods and Materials for Containment and Cleaning Up		<p>For Containment: Contain any spills with dikes or absorbents to prevent migration and entry into sewers or streams. As an immediate precautionary measure, isolate spill or leak area in all directions.</p> <p>Methods for Cleaning Up: Clean up spills immediately and dispose of waste safely. Absorb and/or contain spill with inert material. Do not take up in combustible material such as: saw dust or cellulosic material. Use only non-sparking tools. Transfer spilled material to a suitable container for disposal. Contact competent authorities after a spill.</p>
6.4 Reference to Other Sections		See Section 8 for exposure controls and personal protection and Section 13 for disposal considerations.
SECTION 7: HANDLING AND STORAGE		
7.1 Precautions for Safe Handling		<p>Additional Hazards When Processed: Handle empty containers with care because residual vapors are flammable. May release corrosive vapors.</p> <p>Precautions for Safe Handling: Do not handle until all safety precautions have been read and understood. Wash hands and other exposed areas with mild soap and water before eating, drinking or smoking and when leaving work. Do not get in eyes, on skin, or on clothing. Do not breathe mist, spray, vapors. Take precautionary measures against static discharge. Use only non-sparking tools. Handle empty containers with care because they may still present a hazard. Use appropriate personal protective equipment (PPE).</p> <p>Hygiene Measures: Handle in accordance with good industrial hygiene and safety procedures.</p>
7.2 Conditions for Safe Storage, Including Any Incompatibilities		<p>Technical Measures: Ground and bond container and receiving equipment. Use explosion-proof electrical, ventilating, and lighting equipment. Comply with applicable regulations.</p> <p>Storage Conditions: Keep/Store away from extremely high or low temperatures, direct sunlight, ignition sources, and incompatible materials. Store in a dry, cool and well-ventilated place. Keep container closed when not in use. Keep in fireproof place. Store in original container or corrosive resistant and/or lined container. Store locked up.</p> <p>Incompatible Products: Strong acids, strong bases, strong oxidizers. Halogenated compounds. Acid anhydrides. Aldehydes.</p>
7.3 Specific End Use(s)		Anti-Sludge Agent. For professional use only.

Question	Response	Details
SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION		
8.1 Control Parameters	Isopropyl alcohol (67-63-0) USA ACGIH - ACGIH TWA (ppm) - 200ppm USA ACGIH - ACGIH STEL (ppm) - 400 ppm USA ACGIH - ACGIH chemical category - Not Classifiable as a Human Carcinogen USA ACGIH - Biological Exposure Indices (BEI) - 40 mg/l Parameter: Acetone - Medium: urine - Sampling time: end of shift at end of workweek (background, nonspecific) USA NIOSH - NIOSH REL (TWA) (mg/m ³) - 980 mg/m ³ USA NIOSH - NIOSH REL (TWA) (ppm) - 400 ppm USA NIOSH - NIOSH REL (STEL) (mg/m ³) - 1225 mg/m ³ USA NIOSH - NIOSH REL (STEL) (ppm) - 500 ppm USA IDLH - US IDLH (ppm) - 2000 ppm (10% LEL) USA OSHA - OSHA PEL (TWA) (mg/m ³) - 980 mg/m ³ USA OSHA - OSHA PEL (TWA) (ppm) - 400 ppm	
8.2 Exposure Controls		
8.2.1 Appropriate Engineering Controls	Emergency eye wash fountains and safety showers should be available in the immediate vicinity of any potential exposure. Ensure adequate ventilation, especially in confined areas. Gas detectors should be used when flammable gases or vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Use explosion-proof equipment. Ensure all national/local regulations are observed.	
8.2.2 Personal Protective Equipment (PPE)	Protective clothing. Protective goggles. Gloves. Insufficient ventilation: wear respiratory protection. Face shield.	
Include photos or pictograms of PPEs  Appendix 2		

Question	Response	Details
8.2.3 Materials for Protective Clothing	Chemically resistant materials and fabrics. Wear fire/flare resistant/retardant clothing. Corrosion-proof clothing. Wear protective gloves, Chemical safety goggles, full face shield. If exposure limits are exceeded or irritation is experienced, approved respiratory protection should be worn. In case of inadequate ventilation, oxygen deficient atmosphere, or where exposure levels are not known wear approved respiratory protection.	
8.2.4 Environmental Exposure Controls	Avoid release to the environment.	
8.2.5 Other Information	When using, do not eat, drink or smoke.	
SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES		
9.1 Information on Basic Physical and Chemical Properties		
Physical State	Liquid	
Appearance	Brown	
Odor	Alcohol	
pH	3 - 5 (1% solution)	
Evaporation Rate	No data available	
Melting Point	No data available	
Freezing Point	No data available	
Boiling Point	No data available	
Flash Point	12 °C (53.6 °F)	
9.2 Other Information	No additional information available	
SECTION 10: STABILITY AND REACTIVITY		
10.1 Reactivity	Reacts violently with strong oxidizers. Increased risk of fire or explosion.	
10.2 Chemical Stability	May form flammable or explosive vapor-air mixture.	
10.3 Possibility of Hazardous Reactions	Hazardous polymerization will not occur.	
10.4 Conditions to Avoid	Direct sunlight, extremely high or low temperatures, heat, hot surfaces, sparks, open flames, incompatible materials, and other ignition sources.	

Question	Response	Details
10.5 Incompatible Materials		Strong acids, strong bases, strong oxidizers. Halogenated compounds. Acid anhydrides. Aldehydes.
10.6 Hazardous Decomposition Products		Under normal conditions of storage and use, hazardous decomposition products should not be produced.
SECTION 11: TOXICOLOGICAL INFORMATION		
11.1 Information on Toxicological Effects		<p>Acute Toxicity: Not classified</p> <p>Skin Corrosion/Irritation: Causes severe skin burns and eye damage.</p> <p>pH: 3 - 5 (1% solution)</p> <p>Serious Eye Damage/Irritation: Causes serious eye damage.</p> <p>pH: 3 - 5 (1% solution)</p> <p>Respiratory or Skin Sensitization: Not classified</p> <p>Germ Cell Mutagenicity: Not classified</p> <p>Carcinogenicity: Not classified</p> <p>Reproductive Toxicity: Not classified</p> <p>Specific Target Organ Toxicity (Single Exposure): May cause drowsiness or dizziness.</p> <p>Specific Target Organ Toxicity (Repeated Exposure): Not classified</p> <p>Aspiration Hazard: Not classified</p> <p>Symptoms/Injuries After Inhalation: Inhalation may cause immediate severe irritation progressing quickly to chemical burns. May be corrosive to the respiratory tract. High concentrations may cause central nervous system depression such as dizziness, vomiting, numbness, drowsiness, headache, and similar narcotic symptoms.</p> <p>Symptoms/Injuries After Skin Contact: Causes severe irritation which will progress to chemical burns.</p> <p>Symptoms/Injuries After Eye Contact: Causes severe irritation which will progress to chemical burns. Causes permanent damage to the cornea, iris, or conjunctiva.</p> <p>Symptoms/Injuries After Ingestion: May cause burns or irritation of the linings of the mouth, throat, and gastrointestinal tract.</p> <p>Chronic Symptoms: None known.</p>
SECTION 12: ECOLOGICAL INFORMATION		
12.1 Toxicity		Not classified.
12.2 Persistence and Degradability		Not established.
12.3 Bioaccumulative Potential		Not established.
12.4 Mobility in Soil		No additional information available.
12.5 Other Adverse Effects		Avoid release to the environment.

Question	Response	Details
SECTION 13: DISPOSAL CONSIDERATIONS		
13.1 Waste Treatment Methods	Waste Disposal Recommendations: Dispose of contents/container in accordance with local, regional, national and international regulations. Additional Information: Handle empty containers with care because residual vapors are flammable. Ecology - Waste Materials: Avoid release to the environment.	
SECTION 14: TRANSPORT INFORMATION		
14.1 In Accordance with DOT		
Proper Shipping Name	FLAMMABLE LIQUIDS, CORROSIVE, N.O.S. (Isopropyl alcohol; Benzenesulfonic acid,4-dodecyl-	
Hazard Class	3	
Identification Number	UN2924	
Label Codes	3, 8	
Packing Group	II	
ERG Number	132	
14.2 In Accordance with IMDG		
Proper Shipping Name	FLAMMABLE LIQUID, CORROSIVE, N.O.S. (Isopropyl alcohol; Benzenesulfonic acid,4-dodecyl-)	
Hazard Class	3	
Subsidiary Risk(s)	8	
Identification Number	UN2924	
Packing Group	II	
Label Codes	3, 8	
EmS-No. (Fire)	F-E	
EmS-No. (Spillage) S-C	S-C	
MFAG Number	132	
14.3 In Accordance with IATA		
Proper Shipping Name	FLAMMABLE LIQUID, CORROSIVE, N.O.S. (Isopropyl alcohol; Benzenesulfonic acid,4-dodecyl-)	

Question	Response	Details
Packing Group	II	
Identification Number	UN2924	
Hazard Class	3	
Label Codes	3, 8	
Subsidiary Risk(s)	8	
SECTION 15: REGULATORY INFORMATION		
15.1 US Federal Regulations	<p>SARA Section 311/312 Hazard Classes - Fire hazard, immediate (acute) health hazard</p> <p>Isopropyl alcohol (67-63-0) - Listed on the United States TSCA (Toxic Substances Control Act) inventory</p> <p>Subject to reporting requirements of United States SARA Section 313</p> <p>Benzenesulfonic acid, 4-dodecyl- (121-65-3) - Listed on the United States TSCA (Toxic Substances Control Act) inventory</p>	

Question	Response	Details
15.2 US State Regulations		<p>U.S. - California - SCAQMD - Toxic Air Contaminants - Non-Cancer Acute</p> <p>U.S. - California - SCAQMD - Toxic Air Contaminants - Non-Cancer Chronic</p> <p>U.S. - California - Toxic Air Contaminant List (AB 1807, AB 2728)</p> <p>U.S. - Connecticut - Hazardous Air Pollutants - HLVs (30 min)</p> <p>U.S. - Connecticut - Hazardous Air Pollutants - HLVs (8 hr)</p> <p>U.S. - Connecticut - Volatile Substances</p> <p>U.S. - Idaho - Non-Carcinogenic Toxic Air Pollutants - Acceptable Ambient Concentrations</p> <p>U.S. - Idaho - Non-Carcinogenic Toxic Air Pollutants - Emission Levels (ELs)</p> <p>U.S. - Idaho - Occupational Exposure Limits - TWAs</p> <p>RTK - U.S. - Massachusetts - Right To Know List</p> <p>U.S. - Massachusetts - Toxics Use Reduction Act</p> <p>U.S. - Michigan - Occupational Exposure Limits - STELS</p> <p>U.S. - Michigan - Occupational Exposure Limits - TWAs</p> <p>U.S. - Minnesota - Hazardous Substance List</p> <p>U.S. - Minnesota - Permissible Exposure Limits - STELS</p> <p>U.S. - Minnesota - Permissible Exposure Limits - TWAs</p> <p>U.S. - New Hampshire - Regulated Toxic Air Pollutants - Ambient Air Levels (AALs) - 24-Hour</p> <p>U.S. - New Hampshire - Regulated Toxic Air Pollutants - Ambient Air Levels (AALs) - Annual</p> <p>U.S. - New Jersey - Discharge Prevention - List of Hazardous Substances</p> <p>U.S. - New Jersey - Environmental Hazardous Substances List</p> <p>RTK - U.S. - New Jersey - Right to Know Hazardous Substance List</p> <p>U.S. - New Jersey - Special Health Hazards Substances List</p> <p>U.S. - New York - Occupational Exposure Limits - TWAs</p> <p>U.S. - North Dakota - Air Pollutants - Guideline Concentrations - 1-Hour</p> <p>U.S. - North Dakota - Air Pollutants - Guideline Concentrations - 8-Hour</p> <p>U.S. - Oregon - Permissible Exposure Limits - TWAs</p> <p>U.S. - California - Safer Consumer Products - Initial List of Candidate Chemicals and Chemical Groups</p> <p>RTK - U.S. - Pennsylvania - RTK (Right to Know) - Environmental Hazard List</p> <p>RTK - U.S. - Pennsylvania - RTK (Right to Know) List</p> <p>U.S. - Rhode Island - Air Toxics - Acceptable Ambient Levels - 1-Hour</p> <p>U.S. - Tennessee - Occupational Exposure Limits - STELS</p> <p>U.S. - Tennessee - Occupational Exposure Limits - TWAs</p> <p>U.S. - Texas - City of Austin - Aerosol Paint and Glue Restrictions</p> <p>U.S. - Texas - Effects Screening Levels - Long Term</p> <p>U.S. - Texas - Effects Screening Levels - Short Term</p> <p>U.S. - Vermont - Permissible Exposure Limits - STELS</p> <p>U.S. - Vermont - Permissible Exposure Limits - TWAs</p> <p>U.S. - Washington - Permissible Exposure Limits - STELS</p> <p>U.S. - Washington - Permissible Exposure Limits - TWAs</p>

Question	Response	Details
SECTION 16: OTHER INFORMATION, INCLUDING DATE OF PREPARATION OR LAST REVISION		
Other Information	This document has been prepared in accordance with the SDS requirements of the OSHA Hazard Communication Standard 29 CFR 1910.1200	
GHS Full Text Phrases	<p>Eye Dam. 1 - Serious eye damage/eye irritation Category 1</p> <p>Eye Irrit. 2A - Serious eye damage/eye irritation Category 2A</p> <p>Flam. Liq. 2 - Flammable liquids Category 2</p> <p>Skin Corr. 1B - Skin corrosion/irritation Category 1B</p> <p>STOT SE 3 - Specific target organ toxicity (single exposure) Category 3</p> <p>H225 - Highly flammable liquid and vapor</p> <p>H314 - Causes severe skin burns and eye damage</p> <p>H318 - Causes serious eye damage</p> <p>H319 - Causes serious eye irritation</p> <p>H336 - May cause drowsiness or dizziness</p>	
<p>Disclaimer: This information is based on our current knowledge and is intended to describe the product for the purposes of health, safety and environmental requirements only. It should not therefore be construed as guaranteeing any specific property of the product.</p>		

Media



Appendix 1

Appendix 2