



Site Investigation Report Template

conducted for

West coast project

Location

2370 Humboldt Rd, Chico, CA 95928, USA

Full Name of Investigator

Erick Brent

Date of Investigation

04 Mar 2019 12:47 PM



Completed on

04 Mar 2019 01:13 PM


Score

0/0.0 - 0.00%

Inspection

Question	Response	Details
Site Investigation Report		
Authorization		
I certify that I am the authorized representative and have the authority to grant the investigator access to the property for and authorize the work certified in this site investigation.		
Full Name and Signature of Authorized Representative	John Flores	04 Mar 2019 12:48 PM 
Site Information		
Property Owner	Mary LLC	
Address	2370 Humboldt Rd, Chico, CA 95928, USA	
Latitude & Longitude	39.74001 / -121.793383	
Climate	Sunny	
Elevation	60 meters	
Soil Characterization Method		
Test Hole No.	1	
Texture		
Texture	Loam	
Sand Sizes	Fine	
 Appendix 1		
Structure		
Grade	Strong	

Question	Response	Details
Size	Coarse	
Shape	Granular	
Rock Fragments		
Rock Fragments	Irregular	
Type of Rock	Sandstone	
 <p>Appendix 2</p>		
Terms of Rock	Stratified	
Mottles		
Quantity	Common	
Size	Medium	
Contrast	Distinct	
Boundary		
Distinctness	Gradual	
Topography	Irregular	
Consistency		
Dry	Slightly Hard	
Moist	Friable	
Completion		
Overall Findings	<p>Based on today's site investigation, the site is ideal for our project and there are no foreseeable risks aside from the fire risk west of the city (California fires 2018). Visual inspection do not show soil contamination and no nearby industrial activities. Will still wait for the result of the lab testing of soil samples to be conclusive for the geotechnical report.</p>	

Question	Response	Details	
I certify that I am qualified to conduct and have completed this site investigation to the best of my knowledge.			
Full Name and Signature of Investigator	Erick Brent	04 Mar 2019 12:55 PM	

Media



Appendix 1



Appendix 2