

E616-NeutronGrounds / Primo Camacho / 07 Aug 2019

Complete **Dock Audit Checklist** Inspection score Failed items Created actions 75.00% 2 0 Shipment# and Client E616-NeutronGrounds Inspected by Primo Camacho Conducted on ☐ 7th Aug, 2019 ③ 8:52 AM +08 Location 7 Steeples Rd, Washington Depot, CT, 06794

Failed items 2 Failed

Inspection / Item / Item 1 / Design

Is it the right color?

No

- Notes

Shipping DDP-626 (left) has duller printing on the torso compared to our standard (right). Recommending this for recall.

- Photos



Photo 1

Inspection / Item / Item 2 / Design

Is it the right color?

No

- Notes

Printing in the front is not sharp enough to meet standards. Will send request to review print and cartridges.

- Photos



Photo 2


Inspection 2 Failed 75.00%

Item

Item 1

Product#
DDP-626

Design 1 Failed



Notes

Shipping DDP-626 (left) has duller printing on the torso compared to our standard (right). Recommending this for recall.

- Photos



Photo 1

Physical Inventory Count

Are all product inclusions inside the box as intended and advertised?	Yes
Manual(s) included? (where applicable)	N/A

Special Customer Requirements

Does the product comply with all special customer requirements?	N/A
 Notes There are no special customer requirements but the product does not me. 	neet our standards.

Item 2

Product#
IRN-645

Design 1 Failed

Does the product comply with dimensions specifications?	Yes
No visible scratches, deformities, and/or damage?	Yes
Is it the right color?	No

- Notes

Printing in the front is not sharp enough to meet standards. Will send request to review print and cartridges.

- Photos



Photo 2

Physical Inventory Count

Are all product inclusions inside the box as intended and advertised?	Yes
Manual(s) included? (where applicable)	N/A

Special Customer Requirements

Sign off

Inspector's full name and signature

Primo Camacho

7th Aug, 2019 9:35 AM +08

Photos 2 Photos








Photo 2