



Vince Flanders / Edward Benson / 07 Oct 2019

Smog Checklist

Complete

Failed items	Created actions
0	0
Vehicle Owner Vince Flanders	
Location 13002 Wheeler Pl, Santa Ana, CA 92705, USA	
Prepared by Edward Benson	
Conducted on 📅 7th Oct, 2019 ⌚ 2:33 PM +08	

Smog Check

General Information

Enter VIN # 1B4HS38Z8WF172214
Enter License Plate No. 6TR1234
Enter Mileage 248 miles
Exhaust Configuration, when prompted (Single or Dual) single
Vehicle Make 2017 Ford Fiesta
Body Type 4-door sedan
Vehicle Model Name Ford Fiesta Sedan
Number of Cylinders 4
Engine Size 1,299 cc
Transmission Type 5-speed
Certification Type; (CA, FED, Referee) CA
BAR Referee Label Number 123ABC
Fuel Type gasoline
Engine Make (Motor Homes, Referee) EcoBoost
Engine Year (Motor Homes, Referee) 2017

Take photo of vehicle (optional)

– Photos



Photo 1

Exhaust Emission Test Result

Hydrocarbons ppm (HC)

240

Carbon Monoxide % (CO)

1.3

Oxides of Nitrogen ppm (NOx)


3

COMPLETION

Comments/Recommendations

Vehicle failed the visual and functional inspection

Full Name and Signature of Technician



Edward Benson

7th Oct, 2019 2:48 PM +08

Photos

1 Photos



Photo 1