



Site Hazard Report

Site Hazard Report

Complete

Score	0%	Failed items	0	Actions	3
Audit Title					Kensington 2 Project
Client / Site					Nexus Prime Corp
Conducted on					10th Sep, 2020 2:00 PM +08
Prepared by					Scott Rolf
Location					174 James Boulevard, Kensington

Actions

3 actions

Audit / Hazard observations / Hazard / Hazard 1

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority High | Due 18th Sep, 2020 6:00 AM +08 | Created by SafetyCulture Staff

Ensure that all employees are provided safety harnesses, and other prescribed PPEs.

Audit / Hazard observations / Hazard / Hazard 2

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority Medium | Due 18th Sep, 2020 6:00 PM +08 | Created by SafetyCulture Staff

Ensure that tools, especially when not in use, are sorted and put in an organized box/shelf.

Audit / Hazard observations / Hazard / Hazard 3

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority High | Due 18th Sep, 2020 9:00 AM +08 | Created by SafetyCulture Staff

Inspect all PPEs and replace damaged ones immediately.

Audit

3 actions, 0%

INSTRUCTIONS

1. Add a safety hazard observation by clicking on "Add Hazard"
2. Enter description of hazard
3. Create a Corrective Action by clicking on the paperclip icon and clicking "Action", then enter description, assign to member, set priority and due date
4. Take relevant photos, enter location and date
5. Complete audit by providing digital signature
6. Share your report by exporting as PDF, Word, Excel or Web Link



Hazard observations

3 actions, 0%

Add Hazard Observation

Hazard

3 actions, 0%

Hazard 1

1 action, 0%

Description/ Observation

Found someone working at a height of approximately 20 feet without a safety harness.

Take a photo



Photo 1

Location

3rd level, building 1

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority High | Due 18th Sep, 2020 6:00 AM +08 | Created by SafetyCulture Staff

Ensure that all employees are provided safety harnesses, and other prescribed PPEs.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Hazard 2

1 action, 0%

Description/ Observation

Tools and equipment are thrown together in a box with no organization.

Take a photo



Photo 2

Location

6th level, Main Conference Room

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority Medium | Due 18th Sep, 2020 6:00 PM +08 | Created by SafetyCulture Staff

Ensure that tools, especially when not in use, are sorted and put in an organized box/shelf.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Hazard 3

1 action, 0%

Description/ Observation

Found a damaged hard hat that should no longer be in use.

Take a photo



Photo 3

Location

Parking Lot, Building 2

Assign corrective action?

Yes

To do | Assignee Juhlian Pimping | Priority High | Due 18th Sep, 2020 9:00 AM +08 | Created by SafetyCulture Staff

Inspect all PPEs and replace damaged ones immediately.

Click on paperclip icon above, click "Action", provide description, assign to responsible person (either within or outside your organisation), set priority and due date

Completion

Comments

Found some major safety compliance issues. I have assigned corrective actions to the appropriate person and will be updated once these recommended actions are completed.

Inspected by:



Scott Rolf

10th Sep, 2020 8:46 PM +08

Appendix



Photo 1



Photo 2



Photo 3