



Your Quick Fire Extinguisher Inspection Checklist

SJKYAI Building / Level 3 / Hermione Derren / 1
Aug 2022

Complete

Score	85.71%	Flagged items	2	Actions	1
-------	---------------	---------------	----------	---------	----------

Conducted on

01.08.2022 00:00 PST

Building

SJKYAI Building

Select Floor

Level 3

Full Name of Inspector

Hermione Derren

Location

38 Dunbarton Rd, Concord, NH
03301, USA

Flagged items & Actions

2 flagged, 1 action

Flagged items

2 flagged, 1 action

Inspection / Quick Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Accessibility

Is there adequate signage above the fire extinguisher?

No

A neon/glow-in-the-dark signage would be ideal.

To Do | Assignee SafetyCulture Staff | Priority Medium | Due 01.08.2022 14:40 PST | Created by SafetyCulture Staff

Add a signage above the extinguisher that could help its visibility.

Inspection / Quick Fire Extinguisher Inspection / Fire Extinguisher / Fire Extinguisher 1 / Physical

Is the sticker/label on the cylinder in readable?

No

Sticker has slight tear on the upper part.

Other actions

0 actions

Inspection

2 flagged, 1 action, 85.71%

Quick Fire Extinguisher Inspection

2 flagged, 1 action, 85.71%



Click to add fire extinguisher to be inspected

Fire Extinguisher

2 flagged, 1 action, 85.71%

Fire Extinguisher 1

2 flagged, 1 action, 85.71%

Is there a fire extinguisher on this floor/level?

Yes

Where is this fire extinguisher located on the floor you are on?

The fire extinguisher is located on the wall near the emergency exit.

Accessibility

1 flagged, 1 action, 80%

Take a photo of the fire extinguisher and its storage location from within a few feet.



Photo 1

Is the fire extinguisher easily visible?

Yes

Is there adequate signage above the fire extinguisher?

No

A neon/glow-in-the-dark signage would be ideal.

To Do | Assignee SafetyCulture Staff | Priority Medium | Due 01.08.2022 14:40 PST | Created by SafetyCulture Staff

Add a signage above the extinguisher that could help its visibility.

Is the fire extinguisher elevated from the ground?

Yes

Is the fire extinguisher's immediate surrounding free from

Yes

obstruction?

Is the fire extinguisher easily removable from its bracket/container? (For fire extinguishers inside glass cabinets, it is alright to not move them anymore)

Yes

Physical

1 flagged, 83.33%



Come closer to the fire extinguisher for visual inspection.

Enter Serial Number (e.g. can be found on the inspection tag or somewhere on the cylinder)

BD-091515

Is the cylinder tank and all external metal parts free of corrosion, dents or other signs of damage?

Yes

Is the sticker/label on the cylinder in readable?

No

Sticker has slight tear on the upper part.



Is the hose free of cracks or other signs of damage?

Yes



Have a look at the inside of the nozzle. Does it show any leak?

No



Is the locking pin present and intact?

Yes

Is the seal present and not broken? (The seal's material can be plastic or metal)

Yes

Pressure Gauge

100%

Locate the pressure gauge at the top of the cylinder. Here is an example of a pressure gauge.



Is the pressure gauge pointed within the optimal green range [refer image above]?

Yes

Inspection Tag

100%

Was a completed inspection for the previous month reflected on the inspection tag?

Yes

Completion

Your summary of observations

Fire extinguisher is in a good condition.

Hermione Derren

Hermione Derren
15.08.2022 14:45 PST

Appendix



Photo 1