



VIM AIRLINES INTERNAL SAFETY REPORT

Complete

Score	94.34%	Flagged items	0	Actions	2
-------	--------	---------------	---	---------	---

Audit Title

Pre-flight Safety Check for Night Flight

Document No.

000032

Client / Site

San Francisco International Airport

Conducted on

04.01.2023

Prepared by

Ailbe Nele

Location

San Francisco, CA, USA
(37.7749295, -122.4194155)

Personnel

Ara Christin
Cayetano Olegarius

Actions

2 actions

Audit / DOCUMENTATION

Manuals

No

Manuals on CPR are missing pages.

To Do | Priority Medium | Due 11.01.2023 17:27 PST | Created by SafetyCulture Staff

Look for missing pages or replace CPR manuals.

Audit / SAFETY EQUIPMENT

Flash light

No

We're missing two.

To Do | Priority High | Due 11.01.2023 17:28 PST | Created by SafetyCulture Staff

Restock on flash lights.

Audit

2 actions, 94.34%

A - FLIGHT DECK

66.67%

General conditions

Yes

Emergency exit

No

Emergency exit sign broke suddenly. Probable cause: overheating. Currently placed outside aircraft.



Photo 1

Equipment

Yes

DOCUMENTATION

1 action, 88.89%

Manuals

No

Manuals on CPR are missing pages.

To Do | Priority Medium | Due 11.01.2023 17:27 PST | Created by SafetyCulture Staff

Look for missing pages or replace CPR manuals.

Checklists

Yes

Radio Navigation Charts

Yes

Minimum Equipment List

Yes

Certificate of Registration

Yes

Noise certificate

Yes

AOC or equivalent

Yes

Radio Licence

Yes

Certificate of Airworthiness

Yes

FLIGHT DATA

100%

Flight preparation

Yes

Weight and balance sheet	Yes
--------------------------	-----

SAFETY EQUIPMENT

1 action, 80%

Hand Fire extinguishers	Yes
Life jackets / Flotation devices	Yes
Harness	Yes
Oxygen equipment	Yes
Flash light	No

We're missing two.

To Do | Priority High | Due 11.01.2023 17:28 PST | Created by SafetyCulture Staff

Restock on flash lights.

FLIGHT CREW

100%

Flight crew Licence	Yes
---------------------	-----

JOURNEY LB/TLB OR EQUIVALENT

100%

Journey LB/ TLB or equivalent	Yes
Maintenance release	Yes
Defect notification & rectification	Yes
Pre-Flight Inspection	Yes

B - SAFETY / CABIN

100%

General internal condition	Yes
C.A's station and Rest area	Yes
FAK /MDK	Yes
Hand Fire Extinguishers	Yes
Life jackets / Flotation Device	Yes
Seat belt and Seat condition	Yes

Emergency exit / Light / Mark / Torch	Yes
The emergency exit signs here are working.	
Slides / Life rafts / ELT	Yes
O2 Supply (C.crew & pax)	Yes
Safety instructions	Yes
Cabin crew members	Yes
Access to emergency exits	Yes
Safety of pax baggage	Yes
Seat capacity	Yes

C - AIRCRAFT CONDITION

100%

General external condition	Yes
Doors and hatches	Yes
Flight controls	Yes
Wheels, tyres and Brakes	Yes
Undercarriage	Yes
Wheel well	Yes
Power plant and pylon	Yes
Fan blades	Yes
Propellers	Yes
Obvious repairs	Yes
Obvious unrepaired damage	Yes
Leakage	Yes

D - CARGO

100%

General condition	Yes
Dangerous goods	N/A

No dangerous goods allowed

Safety of cargo on board

Yes

E - GENERAL

100%

General

Yes

Inspector : Anton Koryukov

Ailbe Nele

Ailbe Nele
04.01.2023 17:31 PST

Captain / Airline representative

Hemera Yaeko

Hemera Yaeko
04.01.2023 17:31 PST

Additionally

04.01.2023 18:00 PST

Appendix



Photo 1