



Road Safety Audit Template

2 Feb 2023 / Main Road / Johan Snow

Complete

Score	0%	Flagged items	0	Actions	1
-------	----	---------------	---	---------	---

Road

Main Road

Date and Time conducted

02.02.2023 14:00 PST

Conducted by

Johan Snow

Location

972 Eastern Pkwy, Brooklyn, NY
11213, USA

Actions

1 action

Audit / Needs of vulnerable road users / Needs of vulnerable road users observation / Needs of vulnerable road users observation 1

Description

Has ramps and is accessible to vulnerable road users
Ramps need repair

To Do | Assignee SafetyCulture Staff | Priority Low | Due 09.02.2023 15:43 PST | Created by SafetyCulture Staff

Endorse work order for ramp repair before the week ends.

General

General observation on the site

Afternoon audit, clear skies, rush hour, lots of foot and vehicle traffic. This is the same spot of a road accident last week. Around the same time.

Road function and surroundings

+ Road function observation

Road function observation

Road function observation 1

Photo



Photo 1

Description

Asphalt road needs repair
Zebra paint needs reapplication

Cross sections

+ Cross sections observation

Cross sections observation

Cross sections observation 1

Photo

Description

One-way three traffic lanes

Alignment

+ Alignment observation

Alignment observation

Alignment observation 1

Photo

Description

Sight is unobstructed

Intersections

+ Intersections observation

Intersections observation

Intersections observation 1

Photo



Photo 2

Description

Intersects with Downtown road
Downtown road is the same width
Same foot traffic

Service and rest areas

+ Service and rest areas observation

Service and rest areas observation

Service and rest areas observation 1

Photo

Description

No service area

Double-check with the project manager if this needs to be reevaluated and included in the next improvement project.

Needs of vulnerable road users

1 action

+ Needs of vulnerable road users observation

Needs of vulnerable road users observation

1 action

Needs of vulnerable road users observation 1

1 action

Photo



Photo 3

Description

Has ramps and is accessible to vulnerable road users
Ramps need repair

To Do | Assignee SafetyCulture Staff | Priority Low | Due 09.02.2023 15:43 PST | Created by SafetyCulture Staff

Endorse work order for ramp repair before the week ends.

Traffic signing, marking, and lighting

+ Traffic signing, marking, and lighting observation

Traffic signing, marking, and lighting observation

Traffic signing, marking, and lighting observation 1

Photo



Photo 4

Description

All traffic lights are ideal and working

Road side features and passive safety installations

+ Road side features and passive safety installations observation

Road side features and passive safety installations observation

Road side features and passive safety installations observation 1

Photo

Description

Signages are bright in this part of the city but dim enough even for afternoon traffic

Completion

Comments and recommendations

I recommend immediate repair for the asphalt road to prevent further damage.
Repair the ramps to avoid accidents down the line.
Repaint for zebra lines.

Signature



Johan Snow
02.02.2023 15:41 PST

Appendix



Photo 1



Photo 2



Photo 3



Photo 4