



## General Job Sheet Template

Francis and Company / 28 Apr 2023 / FC-12345 /  
Joe Ruelie

**Complete**

Score	0%	Flagged items	0	Actions	0
<b>Site conducted</b>					Unanswered
<b>Client</b>					Francis and Company
<b>Conducted on (Date and Time)</b>					28.04.2023 15:31 PST
<b>Job no.</b>					FC-12345
<b>Target Completion Date</b>					28.07.2023
<b>Employee (Full Name)</b>					Joe Ruelie
<b>Site Address</b>					5000 Estate Enighed, Independence, KS 67301, USA

## Job sheet

### Description of fault and works carried out

Leaking water pipes (West wing area ) - Fix the leak and determine the cause of leak

### Add photo (optional)



Photo 1

Materials Used : Click Add button

### Item

#### Item 1

<b>Material</b>	12" 40 White PVC Pipe
<b>Part No.</b>	4004-120AB - 5ft
<b>Quantity</b>	1
<b>Cost</b>	\$109.86 each

#### Item 2

<b>Material</b>	Thread seal tape
<b>Part No.</b>	MIL-T-27730A
<b>Quantity</b>	3
<b>Cost</b>	\$8.99 each

### Details of additional works required

Seal all pipe connectors

## Completion

0%

**Total hours rendered** 8 hrs

**Is the job completed?**

No

I replaced broken pipe but unable to finish pipe sealing. To be continued on Monday.

---

**Employee (Full Name and Signature)**



Joe Ruelie  
28.04.2023 15:34 PST

---

Assisted by: Click Add

**Personel**

---

**Personel 1**

---

**Employee (Full Name and Signature)**



John Mike Tansie  
28.04.2023 15:35 PST

---

**Client (Full Name and Signature)**



Francis Co  
28.04.2023 15:35 PST

---

## Media summary



Photo 1