



Fall Protection Site Safety Inspection

MH Construction Company / 6 May 2023 / Hally Meaks

Complete

Score	95.24%	Flagged items	1	Actions	2
-------	---------------	---------------	----------	---------	----------

Client

MH Construction Company

Date and Time of Inspection

06.05.2023 11:00 PST

Inspected by

Hally Meaks

Location

New Jersey, USA
(40.0583238, -74.4056612)

Flagged items & Actions

1 flagged, 2 actions

Flagged items

1 flagged, 1 action

Inspection / Pre-Job

Are safety nets used in place for fall protection systems?

No

Our existing safety nets have recently been checked and didn't meet our minimum safety and quality standards. These need to be replaced ASAP.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 13.05.2023 18:58 PST | Created by SafetyCulture Staff

Replace safety nets to be used in place for fall protection systems.

Other actions

1 action

Inspection / Pre-Job

Are workers suitably trained in using a harness?

Yes

While workers are suitably trained in safely using a harness, our existing training programs and modules need to be updated to be aligned with our recently audited and improved safety management system. Endorsing this as a corrective action for our safety officers to address before the month of May ends.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 13.05.2023 18:56 PST | Created by SafetyCulture Staff

Update training programs and modules on the safe use of harness.

General Information

Description of work

Construction of a two-story commercial building

Take a photo of the work area



Photo 1

List the names of workers

John Smith, Mark Johnson, Sarah Lee, David Nguyen, Emily Brown

Pre-Job

Does the facility have the permit to operate?

Yes

Take a photo of it

Permit to Work
(Issued April 26, 2022)

Photo 2

Do workers have a safe route to their place of work?

Yes

Is the site tidy and well laid out?

Yes

Are all people on site wearing the correct personal protective equipment?

Yes

Are people working on site inducted on the safety procedures?

Yes

Are workers suitably trained in using a harness?

Yes

While workers are suitably trained in safely using a harness, our existing training programs and modules need to be updated to be aligned with our recently audited and improved safety management system. Endorsing this as a corrective action for our safety officers to address before the month of May ends.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 13.05.2023 18:56 PST | Created by SafetyCulture Staff

Update training programs and modules on the safe use of harness.

Are harnesses, lanyards and other safety gear checked and evaluated?

Yes

Are safety tests conducted before the use of harness?

Yes

Are there systems in place for consultation with workers on safety, health and welfare matters?

Yes

Are First-Aid facilities in place and do workers know where they are?

Yes

Are safety nets used in place for fall protection systems?

No

Our existing safety nets have recently been checked and didn't meet our minimum safety and quality standards. These need to be replaced ASAP.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 13.05.2023 18:58 PST | Created by SafetyCulture Staff

Replace safety nets to be used in place for fall protection systems.

Are there no obstructions between the work area and the net?

Yes

Job-in-progress

100%

Is harness worn properly and attached to secure anchorage?

Yes

REFERENCE: Harness worn properly and attached to secure anchorage
[This is an example of how you can use iAuditor to include best practice reference images in your templates to assist with inspections]



Do lanyards, anchorages, and lifelines support standard body weight?

Yes

Does equipment function in accordance with the manufacturer's recommendations?

Yes

Has the worker been assigned a shock-absorbing lanyard for his own use?

Yes

Has the worker been assigned an approved travel restraint or life line rope for his own use?

Yes

Does the worker have his own rope grab?

Yes

Are positioning device systems used so a worker on an elevated surface can have both hands free?

Yes

Post-job

100%

Have any components that have been subjected to an impact been removed from service?

N/A

Are there no suggested change in the equipment used?

Yes

Do workers talk to supervisor about health and safety concerns and possible changes/training?

Yes

Observation

Write down positive observation

All workers were seen wearing the appropriate personal protective equipment, and safety procedures were being followed. The construction site was well laid out and organized.

Recommenadation

Provide recommendation

It is recommended that safety nets be installed as part of the fall protection systems to ensure the safety of workers who may fall from elevated surfaces. Workers should also receive training on the use of positioning device systems to help them work with both hands free while on elevated surfaces. Finally, workers should be reminded to report any health and safety concerns to their supervisor to ensure a safe work environment.

Inspected by (Name and Signature)



Hally Meaks
06.05.2023 18:48 PST

Media summary



Photo 1

**Permit to Work
[Issued April 30, 2023]**

Photo 2